

## **WARNING:**

Norcold has recalled all Model 1200 series refrigerators manufactured prior to October 6, 2010. The purpose of the recall is to remedy a safety related defect by installing a High Temperature Sensor (HTS). Therefore, if you own such a refrigerator and have not had the HTS installed, you should turn off your refrigerator immediately and call the Norcold Recall Department at (800) 767.9101 to make arrangements to have the HTS installed at no charge to you.

If the HTS has been installed and it trips (red light continuously lit), the Refrigerator must always be brought in and checked by a trained technician. It is imperative that you never bypass the HTS.

Norcold had previously recalled 6 cubic foot and 8 cubic foot refrigerators with serial numbers 1038000 to 1099000. If you own one of these refrigerators and you have not had the original cooling unit replaced you should immediately turn off your refrigerator and contact the Norcold Recall Department at 800.767.9101 to make arrangements to have your original cooling unit replaced at no cost to you.

It is essential that if you are experiencing cooling performance issues with your Refrigerator you immediately take it to a dealer and have it checked by a trained Technician.

**FAILURE TO FOLLOW THESE INSTRUCTIONS CAN RESULT IN FIRE, CAUSING PROPERTY DAMAGE, INJURY OR DEATH.**